

Gyrostate Inspection Procedure

The following is our quality inspection procedure for your reference.

1. Weigh 3 to 4 packages first and choose one or two to do further examination



2. Weigh each item and measure the length to make sure the quantity is enough



3. Examine the details to ensure the quality meets your requirement



4. Re-packing the inspected product



5. Measure the carton size (Resize the carton in order to save the container space.)



6. Use strapping to strengthen the package (if needed)

